

TRAXDA 406090

Magneride Bracket installation instructions

The rectangular bracket moves the mount point of the sensor arm up.

1. Remove nut from sensor arm lower mount
2. Install Traxda bracket on arm
3. Use supplied bolt to fasten to arm, fasten bolt into OEM mount holes
4. Attach sensor arm to upper holes in Traxda bracket.
5. Use Traxda nut to mount arm to hole in bracket.
6. 2 holes are available, for different height kits.

