

Traxda 406091 Magneride Bracket installation instructions

The rectangular bracket moves the mount point of the sensor arm up.

1. Remove ball end from control arm
2. Install Traxda bracket on control arm, tabs down
3. Use supplied bolt to fasten to arm, fasten bolt into OEM mount holes
4. Install ball end on Traxda bracket as shown.

